OBJECTID	LocationDescription	Other Location	Condition	Condition Description	Observed Flow	Flow Appearance	Other Flow Description	Odor	Erosion	Scour Protection	Blockage	EndStyle	Material	End_Style	CreatorDate	Creator	EditDate	Editor	GlobalID
1	On Bank		Good	Moss growing in pipe water flow	Trickling	Trickling	A little more than a trickle, more like a steady small stream	No	No	Yes	No	Open out pipe	RCP	Daylight	2020-01-30 15:49:00x0y08	New Out fall 4	2020-02-03 14:34:00x0y08		{7F15BE37D-F689-4864-B69C-B4E41920BF2D}
2	In Water		Fair	1/3 filled with dirt	Trickling	Trickling	A little more than trickling, flow but less than moderate	No	No	No	No	Open through all	RCP	Headwall	2020-01-30 16:26:00x0y08	New Outfall 10	2020-02-03 14:34:00x0y08		{5D0691D7-5E78-4305-8095-9E5A9A9064E6}
3	In Water							No	No	No	No				2020-01-30 13:59:00x0y08	New Outfall 1	2020-02-03 13:59:00x0y08		{1C0FC2AC-8812-4A8B-B4BF-8C9C1362E61BB03}
4	On Bank		Good		Trickling	Trickling		No	No	Yes	No	Half cut pipe	Plastic	Daylight	2020-02-03 13:54:00x0y08	New Outfall 23	2020-02-03 13:54:00x0y08		{C05BE4CA-4E2B-4BDC-9101-8B4B0DC7558C}
5	In Water		Good	Minor debris in pipe			Can't tell if there is flow pipe is half submerged in water	No	No	Yes	Yes	RCP in water	RCP	Daylight	2020-02-03 13:44:00x0y08	New Outfall 21	2020-02-03 13:53:00x0y08		{11E2C76C-C758-42DC-B5B6-600D5D0F0A45}
6	In Water	In retention basin/ stream	Good		Trickling	Standing Water	Standing water/ pipe half full of water	No	No	Yes	No	Open Cut pipe	RCP	Daylight	2020-02-03 13:52:00x0y08	New Outfall 22	2020-02-03 13:52:00x0y08		{F8AA0480-9310-4980-8D83-5B0667BC1F9}
7	Near Bank		Good		Dry	Dry	None	No	No	Yes	No	Open to surface, swale	RCP	Headwall	2020-02-03 14:06:00x0y08	Outfall 8	2020-02-03 14:06:00x0y08		{3EC77A17-1923-4930C-9F5A-421314A4401}
8	On Bank	Swamp			Moderate	Moderate	Pipe has water in it about 10%. Steady flow from pipe	No	No	No	No	Pipe exposed out of ground	RCP	Daylight	2020-02-03 14:42:00x0y08	New Outfall 15	2020-02-03 14:42:00x0y08		{8F90976D-46BF-4464-BC2C-3394B53B71C0}
9	Near Bank	Swamp		Completely plugged	Standing Water	Standing Water	Plugged on standing water around pipe	No	No	No	No	Open pipe	RCP	Daylight	2020-02-03 15:05:00x0y08	New Outfall 16	2020-02-03 15:05:00x0y08		{4A0A0A0A-0A0A-0A0A-0A0A-0A0A0A0A0A0A}
10	In Water	Stream bed	Damaged	Outlet lap of RCP is broken. Around outlet sediment has bee	Trickling	Trickling		No	No	Yes	No	Curved	RCP	Daylight	2020-02-03 15:05:00x0y08	New Outfall 24	2020-02-03 15:05:00x0y08		{8A2E4BD2-C8E3-4548-9F6C-CF4C62313CB3}
11	On Bank	In stream	Fair	Lots of roots at outfall, may b in pipe to. Tree growing right o	Moderate	Moderate		No	No	Yes	No	Open pipe	RCP	Daylight	2020-02-03 15:15:00x0y08	New Outfall 25	2020-02-03 15:17:00x0y08		{B4242406-5A06-4009-AC10-51C779826B9F}
12	Other	Near swamp	Good		Dry	Dry		No	No	Yes	No	Open from ground	Plastic	Daylight	2020-02-03 15:26:00x0y08	New Outfall 26	2020-02-03 15:26:00x0y08		{D158798-4796-4D22-A6E8-F9C0E93135A75}
13	In Water	In swamp	Good		Dry	Standing Water	Probably just groundwater, pipe sitting in water	No	No	No	No	Open PVC from ground	Other	Daylight	2020-02-03 15:41:00x0y08	New Outfall 27	2020-02-03 15:43:00x0y08		{F8329BC6-9E4A-485D-BC69-BC1B19F402A}
14	On Bank	Edge if street	Fair		Dry	Dry		No	No	Yes	No	Open	RCP	Daylight	2020-02-03 15:54:00x0y08	New Outfall 28	2020-02-03 15:54:00x0y08		{D0E7181A-C87A-4F28-9654-6B3DCAB8FC7C}
15	On Bank	Near road	Good	Possible outfall point. Pipe from CB further up the road is at	Dry	Dry		No	No	Yes	No	Open pvc	RCP	Daylight	2020-02-03 16:13:00x0y08	New Outfall 29	2020-02-03 16:22:00x0y08		{EA7EAD4F-4585-4828-9630-5D3272D94C04}
16	On Bank	Edge of road	Good	Pipe is at edge of road	Dry	Dry		No	No	Yes	No	Open on bank	RCP	Daylight	2020-02-03 16:24:00x0y08	New Outfall 30	2020-02-03 16:24:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
17	On Bank	Near road	Good	Culvert from CB 96'downstream	Dry	Dry		No	No	Yes	No	Open	Plastic	Daylight	2020-02-03 16:25:00x0y08	New Outfall 31	2020-02-03 16:25:00x0y08		{C369F019-9A00-4E3C-9E3D-C3B9111C43D}
18	On Bank	Stream	Good	Minor algae in pipe.	Moderate	Moderate	Bubbles in water and around outfall	No	Yes	No	No	Open	OF-231		2020-02-03 16:39:00x0y08	New Outfall 32	2020-02-03 16:39:00x0y08		{C8DCB81A-A4BC-4BB8-8CFC-D91209CB5069}
19	On Bank	In stream	Good	Minor algae growing in pipe	Moderate	Moderate		No	Yes	No	No	Open head wall	RCP	Daylight	2020-02-03 16:50:00x0y08	New Outfall 33	2020-02-03 16:50:00x0y08		{8CDB9D09-FB53-4B2A-A153-CC2BF0F6C01}
20	On Bank	Side of road	Good	Minor algae in pipe	Moderate	Standing Water	Stream	No	No	No	No	Open head wall	Concrete	Daylight	2020-02-03 16:50:00x0y08	OF-233	2020-02-03 16:50:00x0y08		{158E21CD-7F8-4C0d-9F73-B34967147D2d}
21	On Bank		Good		Dry	Dry		No	No	No	No	Open	Plastic		2020-02-03 16:56:00x0y08	New outfall 32	2020-02-03 16:56:00x0y08		{B0AD4A08-8A09-403A-9F83-D3D0A2A8D05}
22	On Bank	Stream	Poor	Water coming out from under pipe due to separated joints, h	Moderate	Moderate		No	No	No	No	Open	RCP	Daylight	2020-02-03 17:05:00x0y08	New Outfall 34	2020-02-03 17:05:00x0y08		{A20979C1-F913-4696-8C80-2C3F82997DC}
23	In Water	In stream	Fair	Upper pipe partially crushed	Trickling	Standing Water	Flowing into pool, pipe 10%full	No	No	No	No	Open	RCP	Headwall	2020-02-03 17:14:00x0y08	New Outfall 35	2020-02-03 17:14:00x0y08		{7D5D6D1D-A7A0-4C2A-9D7D-1FA4C2A9A72F}
25	Other	Side of road	Fair	Plugged needs removing	Dry	Dry		No	Yes	No	No	Open	RCP	Headwall	OF-215	2020-02-03 18:01:00x0y08	New Outfall 36	2020-02-03 18:01:00x0y08		{17F4BB1B-2288-412B-B4D3-AF142E8A0A7B}
26	In retention basin		Good	Pipe is at edge of pond. Clean more often, make retention bas	Trickling	Trickling		No	No	Yes	No	Open	RCP	Headwall	OF-216	2020-02-03 18:08:00x0y08	New Outfall 37	2020-02-03 18:08:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
28	In Water	In swamp	Fair	Lots of green algae? In warmer near outlet water is very gre	Standing Water	Standing Water		No	No	No	No	Out to water	RCP	Headwall	OF-214	2020-02-03 18:21:00x0y08	New Outfall 38	2020-02-03 18:21:00x0y08		{5DCF1C4-9FF8-4C92-A7F7-D0A8D9B6E}
29	In Water	On Bank	Good		Dry	Dry	Water in stream murky/ green	No	No	No	No	Open	Plastic	Headwall	2020-02-03 18:27:00x0y08	New outfall 39	2020-02-03 18:27:00x0y08		{EE872CA8-0762-4B8C-B803-334d3B30A5B3}
30	In Water	Near street	Fair	Sediment fills 30% of Pipe	Trickling	Trickling	Can see oil in water	No	No	No	No	Open to daylight	RCP	Headwall	2020-02-03 18:33:00x0y08	New outfall 38	2020-02-03 18:33:00x0y08		{E0E6C102-4120-4E1F-93BA-00B46C79228B}
31				Not really an outfall. More an inlet CB									OF-208		2020-02-03 18:36:00x0y08		2020-02-03 18:36:00x0y08		{D0061219-2926-493E-B0BF-9E1FBE9B074B}
32	In Water	Near street	Fair	Minor debris in pipe	Standing Water	Standing Water		No	No	No	No	Open to daylight	OF-204	Headwall	2020-02-03 18:39:00x0y08	New Outfall 40	2020-02-03 18:39:00x0y08		{A1A2AE63-7CA1-4803-939E-E03B03B2F9DA}
33	In Water	Near street	Fair	Minor debris in pipe	Standing Water	Standing Water		No	No	No	No	Open	RCP	Headwall	2020-02-03 18:40:00x0y08	New Outfall 41	2020-02-03 18:40:00x0y08		{9984E969-BDD6-48FC-B109-2A5DB12246E}
34	In Water	In swamp	Good		Trickling	Standing Water		No	No	No	No	Open	Corrugated Metal		OF-210	2020-02-03 18:45:00x0y08	New Outfall 42	2020-02-03 18:45:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
35	In Water	In swamp	Good		Trickling	Standing Water		No	No	No	No	Open	Corrugated Metal		OF-211	2020-02-03 18:49:00x0y08	New Outfall 43	2020-02-03 18:49:00x0y08		{4C232783-3A86-4DD9-AAA3-F9b8012D8B66}
36	On Bank	Near street	Good	Minor algae in pipe	Moderate	Moderate	Minor bubbles at outfall	No		No	No	Open	RCP	Daylight	OF-198	2020-02-03 18:54:00x0y08	New Outfall 44	2020-02-03 18:54:00x0y08	|{48fA9A39-ADBC-4E9A-AE0E-39C951709TB4}
37	Other	Can't locate											OF-202		2020-02-03 19:00:00x0y08	New Outfall 45	2020-02-03 19:00:00x0y08		{79F1E32C-E676-4A19-B355-F98F57461C13}
38	On Bank	Stream near road	Good	Not really an outfall more of an inlet fr the stream	Moderate	Moderate	Stream	No		No	No	Open	RCP		2020-02-03 19:04:00x0y08	New Outfall 46	2020-02-03 19:04:00x0y08		{FF91C298-C0A1-4F23-82F3-b489981A82B}
39	In Water	Stream	Fair		Trickling	Trickling	Flows to a deeper slower moving stream, pipe 90% submerg	No		No	No	Open	RCP	Daylight	OF-196	2020-02-03 19:08:00x0y08	New Outfall 47	2020-02-03 19:08:00x0y08		{FD0A5006-7A05-4f25-AA70-B04B0DCC5D0A}
40	Other	Can't find, if it is here it's buried under all the debris the neighbors put out there											OF-207		2020-02-03 19:17:00x0y08		2020-02-03 19:17:00x0y08		{A501033-3031-4302-B863-91D0FFE16986}
41	In Water		Good		Standing Water	Standing Water		No		No	No		Corrugated Metal 75		2020-02-03 19:19:00x0y08	New Outfall 48	2020-02-03 19:19:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
43	Other		Poor	Neighbor said water gets blocked up down stream and causes flooding in yards	Standing Water	Standing Water							RCP		2020-02-03 19:15:00x0y08	New Outfall 49	2020-02-03 19:15:00x0y08		{D4F7390B-23D2-47C2-B75b-3E15AA2B0B9B}
44	In Water		Good		Standing Water	Standing Water		No	No	Yes	No		Corrugated Metal 75		2020-02-03 17:34:00x0y08	New Outfall 68	2020-02-03 17:34:00x0y08		{CA97F875-9B82-47F0-8DAF-D05A382B30A6}
45	In Water		Good		Standing Water	Standing Water		No	No	Yes	No		Corrugated Metal 60		2020-02-03 17:44:00x0y08	New outfall 400	2020-02-03 17:44:00x0y08		{D7DDE81F-638B-446D-A2C2-F0D37F274461}
46	In Water		Good		Standing Water	Standing Water		No	No	Yes	No		Concrete		2020-02-03 17:18:00x0y08	Outfall 401	2020-02-03 17:18:00x0y08		{CDB4D001-5C3A-4F0C-9C8f-0E8E7B9b9B21}
47	Other		Good		Standing Water	Trickling		No			No		Concrete		2020-02-03 17:22:00x0y08	Outfall 403	2020-02-03 17:22:00x0y08		{F39A2CD-BE64-4C60-8172-531382A12BF}
48	In Water		Good	RCP 30"	Trickling	Standing Water		No			No		Concrete		2020-02-03 17:34:00x0y08	Outfall 404	2020-02-03 17:34:00x0y08		{78070A39-BC9F-4CE8-A949-79941E4E7A}
49	In Water		Good	RCP 30"	Trickling	Trickling		No			No		Concrete		2020-02-03 17:40:00x0y08	Outfall 405	2020-02-03 17:40:00x0y08		{7E4B0A2C-F8C3-4B2B-A44B-BCC2F9A11C31}
50	In Water		Good	42" RCP	Standing Water	Trickling		No			No		Concrete		2020-02-03 17:47:00x0y08	Outfall 6	2020-02-03 17:47:00x0y08		{7F4B5AC2-F323-4B28-A44B-BCC2F9A11C31}
51	On Bank		Good	RCP 3/4&1" and 1"	Trickling	Trickling		No			No		Concrete		2020-02-03 17:51:00x0y08	Outfall 8	2020-02-03 17:51:00x0y08		{A4B4479-17F3-44F0-B0B1-0C37B7F1236}
53	On Bank		Good		Standing Water	Standing Water		No			No		Outfall 341		2020-02-03 18:06:00x0y08	New Outfall 341	2020-02-03 18:06:00x0y08		{A43B13D0-8D58-44A8-B6DC-0623B3B76666}
57	Other	In parking lot	Good	18" RCP	Dry	Dry		No	No	No	No	Outfall 365			2020-03-06 15:14:00x0y08	New Outfall 365	2020-03-06 15:14:00x0y08		{61E7B5B0-5815-4CAC-B420-4DCDC2C91163F}
64	On Bank		Good	24" RCP	Standing Water	Standing Water		No	No	Yes	No	Outfall 3112			2020-04-16 02:00:00x0y08	New Outfall 3112	2020-04-16 02:00:00x0y08		{9FDC9DF1-A413-4746-B5F8-4E17CC353D64}
65	Near Bank		Good	x2 18" RCP	Trickling	Trickling		No			No	Other	Concrete		2020-04-23 15:58:00x0y08	Other 1	2020-04-23 15:58:00x0y08		{D279F7CA-0644-4099-9878-833C6A8B31D9}
66				Could not access	Dry	Dry									2020-05-27 15:06:00x0y08	01 SOT JM	2020-05-27 15:06:00x0y08		{7317A42D-0835-4402-8FC4-8D21113B7f9B}
67	Other	Edge of woods	Good		Dry	Dry		No			No	Plastic basin			2020-05-27 16:06:00x0y08	OF2 02T JM	2020-05-27 16:06:00x0y08		{B7542CCA-F312-4BAE-B84D-F9C1C9038A04}
68	In Water		Good		Trickling	Trickling		No			No		Concrete		2020-05-28 15:44:00x0y08	OF 525 JM	2020-05-28 15:44:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
69	In Water		Good	40" RCP	Trickling	Trickling		No			No		RCP		2020-05-28 16:54:00x0y08	OF 526 JM	2020-05-28 16:54:00x0y08		{89AF8763-3A1E-4C2E-A3d3-F2C7D14A4d2}
70	Other			In abundant foliage		Standing Water		No					OF 602 JM		2020-06-02 17:43:00x0y08	03 602 JM	2020-06-02 17:43:00x0y08		{2F21067-DBE1-42AA-A2AF-0370365EB8A6}
71	Other	Cover by foliage	Good		Dry	Dry		No		Yes			RCP		2020-06-02 17:50:00x0y08	OF 602 JM	2020-06-02 17:50:00x0y08		{7A9A2CA-DB7E-4AE1-B54F-2B4549C00CC}
72	Other		Good		Trickling	Trickling		No	No	Yes			OF-217		2020-06-02 13:10:00x0y08	OF-217	2020-06-02 13:10:00x0y08		{E1982B59-5E5E-4A10-9805-42F89203B264}
73	Other		Good		Trickling	Trickling							OF-216		2020-06-02 13:16:00x0y08	OF-216	2020-06-02 13:16:00x0y08		{98EC4C1-72F6-4B21-B148-2A0D8A8B5BC2}
74	Other		Good		Standing Water	Standing Water							OF-212		2020-06-02 13:32:00x0y08	OF-212	2020-06-02 13:32:00x0y08		{2F59345-9728-431A-AA2A-E3366228A9D0}
75	Other		Good										OF-213		2020-06-02 13:40:00x0y08	OF-213	2020-06-02 13:40:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
76	In abundant foliage		Good										OF-203		2020-06-02 13:49:00x0y08	OF-203	2020-06-02 13:49:00x0y08		{31AF2E92-6C15-4CCC-9955-B8FE452B1A44}
77	Other		Good										OF-200		2020-06-02 13:56:00x0y08	OF-200	2020-06-02 13:56:00x0y08		{02800BFA-3BDE-4ACS-B80c-78E581FB6C80}
78	Other		Good	x3 18" RCP	Dry	Dry		No	No	No	No		OF-199		2020-06-02 13:57:00x0y08	OF-199	2020-06-02 13:57:00x0y08		{274B3E3E-8E15-47EF-83A2-3C5BF14954d8}
79	On Bank		Good		Moderate	Moderate							OF-201		2020-06-02 13:59:00x0y08	OF-201	2020-06-02 13:59:00x0y08		{FE814838-8B41-4F9D-A242-0AAA278F54D4}
80	In abundant foliage				Dry	Dry							OF-194		2020-06-02 14:11:00x0y08	OF-194	2020-06-02 14:11:00x0y08		{0A1178D5-D590-49C5-837E-BE0D0F7B32A3}
81	Other		Good		Trickling	Trickling				Yes		Plastic	OF 602 JM		2020-06-02 14:22:00x0y08	01 602 JM	2020-06-02 14:22:00x0y08		{E3B0B2D7-5FCB-9D0F-A47B-BCF21B8D96B3}
82	In Water		Good		Trickling	Standing Water				Yes		Plastic	OF-192		2020-06-02 14:32:00x0y08	OF-192	2020-06-02 14:32:00x0y08		{D0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
83	Other		Poor		Dry	Dry							OF-193		2020-06-02 14:37:00x0y08	OF-193	2020-06-02 14:37:00x0y08		{D0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
84	Other		Poor		Dry	Dry							OF-197		2020-06-02 14:50:00x0y08	OF-197	2020-06-02 14:50:00x0y08		{C11E9D6-D05B-4CEC-919F-F5D1B3C07BB}
85	Other		Good		Standing Water	Standing Water							OF-191		2020-06-02 15:09:00x0y08	OF-191	2020-06-02 15:09:00x0y08		{79A07E1A-1AA4-48B1-9BA2-3A9846f7DAC2}
86	Other		Good		Dry	Dry		No	No	Yes			OF-190		2020-06-02 15:19:00x0y08	OF-190	2020-06-02 15:19:00x0y08		{C81F8991-8001-4868-8C86-354C70C8931}
87	Other		Fair		Dry	Dry		No		Yes			RCP		2020-06-02 15:32:00x0y08	New outfall 54	2020-06-02 15:32:00x0y08		{A0250A56-2608-49DC-92CA-F04D6A38F1}
88	Other		Good		Dry	Dry		No		Yes			RCP		2020-06-03 16:32:00x0y08	New outfall 56	2020-06-03 16:32:00x0y08		{9EA8B300-E789-4F9D-BA1A-6B9d8396E56}
89	Other		Good		Dry	Dry		No		Yes			Concrete		2020-06-03 16:41:00x0y08	New outfall 55	2020-06-03 16:41:00x0y08		{93DE8B8A-6B6b-41C-9B24-87BDC5B99f4A}
90	Other	In abundant foliage			Dry	Trickling							Concrete		2020-06-03 16:49:00x0y08	New outfall 51	2020-06-03 16:49:00x0y08		{CC373A56-0574-415A-BC43-E88B6DA5BBF9}
91	Other		Fair		Dry	Trickling		No	No	Yes	Yes	RCP	RCP		2020-06-03 17:00:00x0y08	New outfall 52	2020-06-03 17:00:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
92	In Water		Good		Trickling	Standing Water		No	No	Yes	No		RCP		2020-06-03 17:05:00x0y08	Outfall 76	2020-06-03 17:05:00x0y08		{E4A9ADD3-8d46-44D2-937A-D8443d2B6b2}
93	Other	In abundant foliage				Dry							Concrete		2020-06-03 17:12:00x0y08	New outfall 60	2020-06-03 17:12:00x0y08		{97232143-33A2-6886-B9F4-C3B7142DD6B5}
94	Other	In abundant foliage				Standing Water							RCP		2020-06-03 17:21:00x0y08	New outfall 61	2020-06-03 17:21:00x0y08		{D2F2E3b-71eC-46C0-9F9B-5FF53D0A8B6}
95	Other	In abundant foliage				Standing Water							RCP		2020-06-03 17:27:00x0y08	New outfall 123	2020-06-03 17:27:00x0y08		{8EF12B00-EAD1-4132-8B0c-6EC18D714E59}
96	Other	In abundant foliage				Standing Water							RCP		2020-06-03 17:36:00x0y08	New outfall 115	2020-06-03 17:36:00x0y08		{9B3A8A35-0548-4F70-8C91-99FA32CA3843}
97	In Water		Good		Standing Water	Standing Water		No	No	Yes	No		Concrete		2020-06-03 17:42:00x0y08	New outfall 115	2020-06-03 17:42:00x0y08		{E88A91FF-C2BB-4520-A3B3-9804C40D3D36}
98	In abundant foliage		Good		Trickling	Trickling		No	No		No		RCP		2020-06-03 17:49:00x0y08	New outfall 76	2020-06-03 17:49:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
99	Other		Good		Standing Water	Standing Water		No	No	No	No		RCP		2020-06-03 18:01:00x0y08	New outfall 77	2020-06-03 18:01:00x0y08		{9F3F1167-8B48-4B52-8E6E-4D8B9A8A1F7}
100	Other		Good		Dry	Dry		No	No	Yes	No		RCP		2020-06-03 18:04:00x0y08	New outfall 80	2020-06-03 18:04:00x0y08		{432A9B66-7E08-466C-8A07-B1E2EF297B5b}
101	Other		Good		Dry	Dry				Yes			OF-220		2020-06-03 13:40:00x0y08		2020-06-03 13:40:00x0y08		{9f6B97F4-C8A4F-4A8D-BFF6-B8A7C761402B}
102	Other	In woods				Standing Water	Downward flow						Concrete		2020-06-03 13:50:00x0y08	Outfall 361	2020-06-03 13:50:00x0y08		{D2C48A1E-4DDC-4F9D-5F0C-5723CE9BA609}
103	In Water		Good		Trickling	Trickling		No			No		Outfall 362		2020-06-03 13:55:00x0y08	Outfall 362	2020-06-03 13:55:00x0y08		{B5B6055-B415-494A-A4AA-2A22FAAF711}
104	Other	Located in backyard						No			No		Plastic		2020-06-03 14:01:00x0y08	Outfall 363	2020-06-03 14:01:00x0y08		{9F69325-8D6B-455b-A460-5BD4A255F3D}
105	In Water		Good		Standing Water	Standing Water		No			No		Outfall 364		2020-06-03 14:08:00x0y08	Outfall 364	2020-06-03 14:08:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
106	In Water		Good		Trickling	Trickling		No			No		Outfall 365		2020-06-03 14:21:00x0y08	Outfall 365	2020-06-03 14:21:00x0y08		{B4AC64e-18F3-46F8-9908-CA8BEB3B6A1}
107	Other					Dry							OF-218		2020-06-03 14:29:00x0y08		2020-06-03 14:29:00x0y08		{99BC9683-3F75-4044-8035-1936TABF1C96}
108	Other	In foliage, could not access				Dry							Outfall 392		2020-06-03 14:40:00x0y08	Outfall 392	2020-06-03 14:40:00x0y08		{1DDEB371-9A07-4287-9037-B0E6F4D3C017}
109	In Water		Fair		Trickling	Trickling		No	Yes	No	Yes	Corrugated Metal	Outfall 393		2020-06-03 14:54:00x0y08	Outfall 393	2020-06-03 14:54:00x0y08		{8B2C4E69-993F-4F2A-A588-2660B9FAD4A2}
110	In Water		Good		Trickling	Trickling		No	No	Yes	No	RCP	Outfall 394		2020-06-03 15:01:00x0y08	Outfall 394	2020-06-03 15:01:00x0y08		{B3E2B09A-9B02-4C2B-2C2B-C0285C327100}
111	In Water		Good	3 Outfalls - 2 Plastic, 1 Concrete	Standing Water	Standing Water		No	No	No	No	Outfall 3910		2020-06-03 15:19:00x0y08	New Outfall 60	2020-06-03 15:19:00x0y08		{A2731df-1-1182-4C0E-A9E4-092A929ABAC0}
112	Other		Good	2 Outfalls - 1 Concrete, 1 Plastic	Dry	Dry		No	No	No	No	Outfall 395		2020-06-03 15:26:00x0y08	Outfall 395	2020-06-03 15:26:00x0y08		{3A75F9Ae-A2E4-4A93-D95AA9B5BE2}
113	Other	In foliage				Trickling						RCP	OF-219		2020-06-03 15:53:00x0y08		2020-06-03 15:53:00x0y08		{13ADF71b-A07b-4d4A-AB21-c9F0CCAAED5A}
114	In Water		Poor	15" Concrete	Standing Water	Standing Water		No	No	No	Yes	Corrugated Metal	Concrete		2020-06-04 12:41:00x0y08	New outfall 95	2020-06-04 12:41:00x0y08		{D0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
115	In Water	Stream	Damaged	Under water	Standing Water	Standing Water		No	No	No	Yes	Corrugated Metal	Concrete		2020-06-04 15:56:00x0y08	New outfall 95	2020-06-04 15:56:00x0y08		{D145EB59-F84D-4C03-95CA-A27539BCE310}
116	Other		Fair	20" RCP	Dry	Dry							OF-188		2020-06-04 16:13:00x0y08		2020-06-04 16:14:00x0y08		{CBC757AB-8BC3-4A0c-971B-D0A076A4198C}
117	In abundant foliage					Dry							OF-193		2020-06-04 16:28:00x0y08		2020-06-04 16:28:00x0y08		{D50FF2AA-AF6b-4493-b4CA-A4CB5A9BC5A8}
118	Other												New OF 361		2020-06-04 17:02:00x0y08		2020-06-04 17:04:00x0y08		{89DD51D4-A113-427F-9226-C8F16DAF96D}
119	In abundant foliage		Good	24" RCP	Standing Water	Dry		No	No				27 608 JM		2020-06-08 12:01:00x0y08	27 608 JM	2020-06-08 12:01:00x0y08		{4C7B1187-2E52-4EC4-B914-0179CF7AA32D}
120	Other	In abundant foliage		15" RCP		Dry							01 608 JM		2020-06-08 12:51:00x0y08	01 608 JM	2020-06-08 12:51:00x0y08		{41FC2D59-919F-4F4E-B17B-A3DD47D56C46}
121	Other	In abundant foliage		24" RCP		Dry							02 608 JM		2020-06-08 13:00:00x0y08	02 608 JM	2020-06-08 13:00:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
122	Other	In abundant foliage		24" RCP	Standing Water	Standing Water							03 608 JM		2020-06-08 13:05:00x0y08	03 608 JM	2020-06-08 13:05:00x0y08		{A9B7F9ff-2A85-4F8-B729-A2F921C2F9C3B}
123	Other	In abundant foliage		20" RCP		Dry							04 608 JM		2020-06-08 13:05:00x0y08	04 608 JM	2020-06-08 13:05:00x0y08		{95D46BAA-A4B7-4CB3-9927-B1BAF8846B6}
124	Other	In abundant foliage		30" RCP		Standing Water							05 608 JM		2020-06-08 13:11:00x0y08	05 608 JM	2020-06-08 13:11:00x0y08		{53A8B28d-D6D1-464F-A64A-AA7BAE71E803}
125	Other	In abundant foliage		30" RCP		Standing Water							06 608 JM		2020-06-08 13:16:00x0y08	06 608 JM	2020-06-08 13:16:00x0y08		{5D39E54d-0A28-4B62-B586-8F5ABC180004}
126			Good	20" Concrete	Dry	Dry		No	No	Yes	Yes	RCP	Concrete		2020-06-08 13:35:00x0y08	07 608 JM	2020-06-08 13:35:00x0y08		{56B0154-8F62-4F4E-A70A-58E1985f7851}
127	Other	In abundant foliage		24" RCP	Dry	Dry							08 608 JM		2020-06-08 13:38:00x0y08	08 608 JM	2020-06-08 13:38:00x0y08		{A42d867c-AF0b-4890-A29E-BF015794F17B5}
128	Other		Good	24" Concrete	Trickling	Trickling		No	No	Yes	No	RCP	Concrete		2020-06-08 13:45:00x0y08	09 608 JM	2020-06-08 13:45:00x0y08		{A0A0A0A0-A0A0-A0A0-A0A0-A0A0A0A0A0A0}
129	In Water		Good	15" Concrete	Trickling	Trickling		No	No	Yes	No	Concrete	Concrete		2020-06-08 13:56:00x0y08	10 608 JM	2020-06-08 13:56:00x0y08		{A46CF18b-214-4C28-8B66-a132384B9B9}
130	In abundant foliage			30" RCP	Moderate	Moderate							11 608 JM		2020-06-08 13:59:00x0y08	11 608 JM	2020-06-08 13:59:00x0y08		{A3776482-D23B-4505-B92A-0B63DC26D4B}
131	In Water		Good	24" RCP	Standing Water	Standing Water		No	No	No	No		12 608 JM		2020-06-08 14:11:00x0y08	12 608 JM	2020-06-08 14:11:00x0y08		{AC167EF-2795-4E3E-8EF5-C1A0B06F4D8}
132	Other			24" RCP		Dry							13 608 JM		2020-06-08 14:13:00x0y08	13 608 JM	2020-06-08 14:13:00x0y08		{AC385782-EF37-46DF-B1A8-37BE3DFA4151}
133	In Water		Fair	20" RCP. Neighbor complains of moderate flooding	Standing Water	Standing Water		No	Yes	No	No		14 608 JM		2020-06-08 14:28:00x0y08	14 608 JM	2020-06-08 14:28:00x0y08		{397342d-9805-494E-ACEF-C8648B22d46E}
134	Other		Good	15" RCP	Dry	Dry							15 608 JM		2020-06-08 14:33:00x0y08	15 608 JM	2020-06-08 14:33:00x0y08		{D19F0D6E-DF19-4FfE-9403-A85DF5B93F7B}
135	In fenced backyard			20" RCP		Dry							16 608 JM		2020-06-08 14:36:00x0y08	16 608 JM	2020-06-08 14:36:00x0y08		{D0F0D77d-F75-4302-B9C5-92109568F19}
136	In Water		Poor	15" RCP	Standing Water	Trickling							17 608 JM		2020-06-08 14:41:

322 Other	Could not access/blocked by foliage				Dry						RCP	29.61in	2020-06-16 17:28 rockyhill		2020-06-16 17:28 rockyhill	{30BF8394-13AC-4B40-8FCB-C162F738F3F1}
323 In Water	In residential yard	15" RCP	Standing Water	Standing Water		No	No	No	No		RCP	30.61in	2020-06-16 17:38 rockyhill		2020-06-16 17:38 rockyhill	{81A1F3B8-1EFE-4D13-9359-8B3A8B5D5A87}
324 Other	In abundant foliage			Dry							RCP	31.61in	2020-06-16 17:44 rockyhill		2020-06-16 17:44 rockyhill	{351C79F-D762-4058-B65F-F940F6AA0B6C}
325 Other	Fenced in by barbed wire	18" RCP	Dry	Dry	Dry	No	No	No	No		RCP	32.61in	2020-06-16 17:48 rockyhill		2020-06-16 17:48 rockyhill	{F52AC117-8A34-49FF-A37F-211283C51B}
326 Other		15" plastic	Dry	Dry	Dry	No	No	No	No		Plastic	33.61in	2020-06-16 17:57 rockyhill		2020-06-16 17:57 rockyhill	{E78E4788-6360-4BC3-8ADE-1CD3D7D63983}
327 Other	In abundant foliage			Dry	Dry						RCP	34.61in	2020-06-16 18:01 rockyhill		2020-06-16 18:01 rockyhill	{2CAAF70F-0D56-42EE-8F73-C3B1F3B12551}
328 Other		15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	01.61in	2020-06-16 13:49 rockyhill		2020-06-16 13:49 rockyhill	{2FCF12C2-1F86-42DE-A8A7-9F2D87D01E4}
329 Other		15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	02.61in	2020-06-16 13:55 rockyhill		2020-06-16 13:55 rockyhill	{95CA6A53-E8BA-4119-9F05-57E0AA157148}
330 Other	In residential yard			Dry	Dry						RCP	03.61in	2020-06-16 13:54 rockyhill		2020-06-16 13:54 rockyhill	{F485F082-20C3-4F70-9556-2E2727F0E836}
331 Other		30" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	04.61in	2020-06-16 14:00 rockyhill		2020-06-16 14:00 rockyhill	{A9A7A7A8-0A7A-4B7A-A7A7-A9A7A7A7A7A7}
332 Other		15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	05.61in	2020-06-16 14:05 rockyhill		2020-06-16 14:05 rockyhill	{74C9E1B-14F6-4A43-A4A3-F0B691553A17}
333 Other	Severely blocked	15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	06.61in	2020-06-16 14:02 rockyhill		2020-06-16 14:02 rockyhill	{799B611D-7ED1-4059-9C7F-4B7BB8106E2}
334 Other	In residential yard	15" RCP			Standing Water						RCP	07.61in	2020-06-17 13:00 rockyhill		2020-06-17 13:00 rockyhill	{700785A-D49A-4188-A448-8BEBF0288F67}
335 Other	In abundant foliage				Dry						RCP	02.61in	2020-06-17 13:06 rockyhill		2020-06-17 13:06 rockyhill	{960DF2D9-1F44-41A3-A3D0-5BC6D189CCC}
336 In Water		22" RCP	Standing Water	Standing Water	Standing Water	No	Yes	No	No		RCP	03.61in	2020-06-17 13:10 rockyhill		2020-06-17 13:10 rockyhill	{D9AB3A42-6E59-4857-813C-507D3C3E3B9A}
337 In Water	Good	30" RCP	Standing Water	Standing Water	Dry	No	No	No	No		RCP	04.61in	2020-06-17 13:12 rockyhill		2020-06-17 13:12 rockyhill	{49B11B6A-A1C4-44D3-571F-5132B9F86F3}
338 Other	Blocked by leaves	30" RCP	Dry	Dry	Dry	No	No	No	No		RCP	05.61in	2020-06-17 13:19 rockyhill		2020-06-17 13:19 rockyhill	{2A2A2A2A-2A2A-2A2A-2A2A-2A2A2A2A2A2A}
339 Other	Good	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	06.61in	2020-06-17 13:31 rockyhill		2020-06-17 13:31 rockyhill	{A29F46E-CE2F-4441-A8B5-2B1107187978}
340 Other	Severely blocked	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	07.61in	2020-06-17 13:32 rockyhill		2020-06-17 13:32 rockyhill	{F772BCF4-140C-4768-95C1-EAF3D147BA85}
341 Other	Good	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	08.61in	2020-06-17 13:35 rockyhill		2020-06-17 13:35 rockyhill	{5C2F4A96-AF93-49F8-8427-17A3F3D6A6D8}
342 Other		15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	09.61in	2020-06-17 13:37 rockyhill		2020-06-17 13:37 rockyhill	{A2F3E3D2-4287-4008-B15A-F86CFEB1A6E0}
343 Other	In abundant foliage	20" plastic		Trickling							Plastic	12.61in	2020-06-17 13:39 rockyhill		2020-06-17 13:39 rockyhill	{1BB8C868-BAA2-4491-8E58-7E52A35B5143}
344 Other	In abundant foliage			Standing Water							Plastic	13.61in	2020-06-17 13:54 rockyhill		2020-06-17 13:54 rockyhill	{F3631A1A-7883-49AD-BD66-B7DCE7CFEC0A}
345 Other	Could not locate			Dry							Plastic	14.61in	2020-06-17 14:00 rockyhill		2020-06-17 14:00 rockyhill	{F5CD7C0A-A6C2-4A9F-9A7A-A7A7A7A7A7A7}
346 Other	In residential yard	15" RCP		Standing Water							RCP	15.61in	2020-06-17 14:02 rockyhill		2020-06-17 14:02 rockyhill	{A7A8A7A8-2262-4F9F-9A7A-A7A7A7A7A7AC}
347 Near Bank	Good	15" RCP	Dry	Dry		No	No	No	No		RCP	16.61in	2020-06-17 14:05 rockyhill		2020-06-17 14:05 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
348 On Bank	Good	15" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	17.61in	2020-06-17 14:11 rockyhill		2020-06-17 14:11 rockyhill	{F2355B1F-1995-49AA-918A-2D8488B4A9B6}
349 In Water	Good	15" RCP	Standing Water	Standing Water	Standing Water	No	No	Yes	No		RCP	18.61in	2020-06-17 14:22 rockyhill		2020-06-17 14:22 rockyhill	{D8302AF1-8DF6-4579-B996-0B1728D9A1C}
350 In Water	Good	15" RCP	Standing Water	Standing Water	Standing Water	No	No	Yes	No		RCP	19.61in	2020-06-17 14:24 rockyhill		2020-06-17 14:24 rockyhill	{79F9E3E2D-D3A3-4748-9827-D46A99F52172}
351 Other	In residential yard			Dry	Dry						RCP	20.61in	2020-06-17 14:31 rockyhill		2020-06-17 14:31 rockyhill	{472F82D0-A922-4D8C-A9FF-232101317218}
352 In Water		x1 20" Metal x1 45° concrete	Standing Water	Standing Water	Standing Water	No	No	No	No		Concrete	22.61in	2020-06-17 14:38 rockyhill		2020-06-17 14:38 rockyhill	{99FA0FA1-5188-4475-B5BA-421597E5E016}
353 In Water	Good	Same pipes across the street	Standing Water	Standing Water	Standing Water	No	No	Yes	No		Concrete	21.61in	2020-06-17 14:40 rockyhill		2020-06-17 14:40 rockyhill	{CE85D0A1-E8B8-4486-9533-D24CD43BAF72}
354 In Water	Good	30" RCP	Dry	Dry	Dry	No	No	No	No		RCP	22.61in	2020-06-17 14:45 rockyhill		2020-06-17 14:45 rockyhill	{A7A7A7A7-A7A7-4B7A-A7A7-A7A7A7A7A7A7}
355 In Water	Good	30" RCP	Trickling	Trickling	Dry	No	No	No	No		RCP	23.61in	2020-06-17 14:53 rockyhill		2020-06-17 14:53 rockyhill	{D1686031-E99C-4898-B39b-16bA2B56AA40}
356 In Water	Good	30" RCP	Moderate	Moderate	Moderate	No	No	No	No		RCP	25.61in	2020-06-17 14:55 rockyhill		2020-06-17 14:55 rockyhill	{B0744403-90DB-4968-B402-4996EB0D3B06}
357 Other		18" RCP	Dry	Dry	Dry						RCP	26.61in	2020-06-17 15:01 rockyhill		2020-06-17 15:01 rockyhill	{B4FAC771-310B-4D08-9F4A-4CD7373DBF98}
358 In Water	Good	x1 15" corrugated plastic/ x30 RCP	Standing Water	Standing Water	Standing Water						RCP	27.61in	2020-06-17 15:05 rockyhill		2020-06-17 15:05 rockyhill	{BC80D574-3AAC-4BAD-9391-07D2A3493F0B}
359 In Water	Good	30" RCP	Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	28.61in	2020-06-17 15:07 rockyhill		2020-06-17 15:07 rockyhill	{C78ED05C-DC5A-4986-9614-5A0125513598}
360 Other	Severely blocked	15" RCP	Dry	Dry	Dry						RCP	29.61in	2020-06-17 15:25 rockyhill		2020-06-17 15:25 rockyhill	{B49507D8-B869-4AF9-8290-7527C6D45572}
361 Other	Severely blocked	15" RCP	Dry	Dry	Dry						RCP	30.61in	2020-06-17 15:27 rockyhill		2020-06-17 15:27 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
362 Other	Good	30" RCP	Dry	Dry	Dry						RCP	31.61in	2020-06-17 15:47 rockyhill		2020-06-17 15:47 rockyhill	{6D31903B-4843-46BF-9E8D-0365A8738C23}
363 Other	In abundant foliage			Dry	Dry						Corrugated Metal	32.61in	2020-06-17 15:52 rockyhill		2020-06-17 15:52 rockyhill	{94AF356-EEC2-4B3D-96C4-50C46F9E3E0F}
364 In Water	Good	20" RCP	Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	33.61in	2020-06-17 15:59 rockyhill		2020-06-17 15:59 rockyhill	{8E0B4E3c-C40C-4D3E-9658-1A8F94F2B1C1}
365 Other	In abundant foliage			Dry	Dry						RCP	34.61in	2020-06-17 16:04 rockyhill		2020-06-17 16:04 rockyhill	{27674F9E-09C0-4C4E-9E06-4BCF8E76D0A5}
366 On Bank	Good	15" RCP	Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	35.61in	2020-06-17 16:06 rockyhill		2020-06-17 16:06 rockyhill	{B311B6CC-6A38-4D80-8855-89AD0AAF0A3B}
367 Other	Good	15" RCP	Standing Water	Standing Water	Standing Water	No	No	Yes	No		RCP	36.61in	2020-06-17 16:10 rockyhill		2020-06-17 16:10 rockyhill	{9F15268B-8FCF-474A7-A128-02F97BB5BFC8}
368 In Water	Good	15" RCP	Standing Water	Standing Water	Standing Water	No	No	Yes	No		RCP	37.61in	2020-06-17 16:14 rockyhill		2020-06-17 16:14 rockyhill	{227F7A48-4D4D-4B7A-A7A7-A7A7A7A7A7A7}
369 In Water	Blocked by foliage	Same as 37.61?		Standing Water							RCP	38.61in	2020-06-17 16:16 rockyhill		2020-06-17 16:16 rockyhill	{9B4B2C2-4B4D-4B94-A028-FCA0C24E4A7C}
370 On Bank	Good	30" RCP	Moderate	Moderate	Moderate	No	No	No	No		RCP	39.61in	2020-06-17 16:24 rockyhill		2020-06-17 16:24 rockyhill	{B6A7A7A7-0D7D-4D86-94F1-757A07F91196}
371 In Water	Good	30" RCP	Trickling	Trickling	Dry	No	No	No	No		RCP	40.61in	2020-06-17 16:26 rockyhill		2020-06-17 16:26 rockyhill	{D9F76ECF-A8A4-4B28-93A6-E58F16BF0286}
372 Other	In abundant foliage			Dry	Dry						RCP	41.61in	2020-06-17 16:37 rockyhill		2020-06-17 16:37 rockyhill	{2BA1F0B6-0019-4663-BCB6-E6A61582ADE0}
373 Other	Good	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	42.61in	2020-06-17 16:49 rockyhill		2020-06-17 16:49 rockyhill	{DCC1CA75-154C-4F70-92DF-4FFD5391BCB7}
374 Other	Good	20" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	43.61in	2020-06-17 16:51 rockyhill		2020-06-17 16:51 rockyhill	{890E6880-8CB8-4968-A725-4AD7D6E22352}
375 Other	Could not locate				Dry						RCP	44.61in	2020-06-17 17:24 rockyhill		2020-06-17 17:24 rockyhill	{A2D7B01b-73B0-4783-9B5b-7FBBAA73F765}
376 Other	In residential yard			Dry	Dry						RCP	45.61in	2020-06-17 17:29 rockyhill		2020-06-17 17:29 rockyhill	{12D2D114-737T-4D31-8125-78DD70B6C0f9}
377 Other	Good	x2 15 RCP	Dry	Dry	Dry						RCP	46.61in	2020-06-17 17:32 rockyhill		2020-06-17 17:32 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
378 Other	Good	15" RCP	Dry	Dry	Dry						RCP	11.61in	2020-06-17 13:43 rockyhill		2020-06-17 13:43 rockyhill	{F2A8227D-3CBB-4A8B-998D-6D6DDC1BDFf8}
379 Other	Good	20" RCP	Trickling	Trickling	Trickling						RCP	12.61in	2020-06-17 13:49 rockyhill		2020-06-17 13:49 rockyhill	{47DB4FF3-3C21-C4D3-BFF9-0ED0C2FDE006}
380 Other	Good	24" RCP	Dry	Dry	Dry						RCP	13.61in	2020-06-17 13:51 rockyhill		2020-06-17 13:51 rockyhill	{20A87142-4997-45F1-9357-A6272F71A0E}
381 On Bank	Good	20" RCP	Trickling	Trickling	Dry	No	No	No	No		RCP	06.61in	2020-06-17 13:29 rockyhill		2020-06-17 13:29 rockyhill	{9CD4B106-4B3D-4A25-886F-03689BF0E5E3}
On residential property		x2 15" plastic	Dry	Dry	Dry	No	No	No	No		Plastic	07.61in	2020-06-17 13:35 rockyhill		2020-06-17 13:35 rockyhill	{31167A25-7ED5-401f-8B2B-5299D75C79D}
382 Other	Severely blocked	15" RCP	Dry	Dry	Dry						RCP	08.61in	2020-06-17 13:39 rockyhill		2020-06-17 13:39 rockyhill	{09C5257E-3631-1A6C-9CA3-1A7A0DF7C300}
383 Other	Severely blocked	15" RCP	Dry	Dry	Dry						Corrugated Metal	09.61in	2020-06-17 13:44 rockyhill		2020-06-17 13:44 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
384 In Water	Good	30" concrete	Trickling	Trickling	Trickling	No	No	No	No		Concrete	10.61in	2020-06-17 13:46 rockyhill		2020-06-17 13:46 rockyhill	{CBDE1C12-3C28-4C49-B357-5A0D2384D2C1}
385 In Water	Good	30" concrete	Trickling	Trickling	Trickling	No	No	No	No		Concrete	11.61in	2020-06-17 13:49 rockyhill		2020-06-17 13:49 rockyhill	{AA8CB538-B07F-4A6C-B031-87D01B15F59F7}
386 In Water	Good	30" concrete	Trickling	Trickling	Trickling	No	No	No	No		Concrete	12.61in	2020-06-17 13:52 rockyhill		2020-06-17 13:52 rockyhill	{84TCB350-1E36-481C-B0F5-41931285BFF4}
387 In Water	Blocked by abundant foliage			Standing Water							RCP	13.61in	2020-06-17 13:55 rockyhill		2020-06-17 13:55 rockyhill	{EF027108-186C-42C1-9032-F4F2A7B58A95}
388 Other	In abundant foliage			Dry							RCP	14.61in	2020-06-17 14:07 rockyhill		2020-06-17 14:07 rockyhill	{E3C221A-55CA-44F8-B24E-0b4417C72950}
389 Other	Fenced in			Standing Water							RCP	15.61in	2020-06-17 14:11 rockyhill		2020-06-17 14:11 rockyhill	{354520A2-D927-4060-A5BE-CB6A4E157C45}
390 On Bank		20" RCP	Trickling	Trickling	Trickling	No	No	Yes	No		RCP	16.61in	2020-06-17 14:14 rockyhill		2020-06-17 14:14 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
391 Near Bank	Good	15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	17.61in	2020-06-17 14:53 rockyhill		2020-06-17 14:53 rockyhill	{A2A3B57-1BCa-4F4A-A82B-B5373F6BE5C6}
392 Near Bank	Good	15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	18.61in	2020-06-17 14:55 rockyhill		2020-06-17 14:55 rockyhill	{A2A3B57-1BCa-4F4A-A82B-B5373F6BE5C6}
393 Other	Good	15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	19.61in	2020-06-17 14:58 rockyhill		2020-06-17 14:58 rockyhill	{9B1180A-0F84-479C-5764-8D43751215D6}
394 In Water		30" concrete	Standing Water	Standing Water	Standing Water	No	No	No	No		Concrete	20.61in	2020-06-17 15:00 rockyhill		2020-06-17 15:00 rockyhill	{1D6301F7-A45-4911-91DF-d20B6A9667B}
395 In Water	Good	30" concrete	Trickling	Trickling	Trickling	No	Yes	Yes	No		Concrete	20.61in	2020-06-17 15:05 rockyhill		2020-06-17 15:05 rockyhill	{275F60A-5882-487F-8D9A-0CB11F8CD09B}
396 In Water	Setback in foliage	30" concrete	Trickling	Trickling	Trickling	No	Yes	Yes	No		Concrete	21.61in	2020-06-17 15:01 rockyhill		2020-06-17 15:01 rockyhill	{14F8C246-1988-4BCF-8031-4C86F5D3E3B8}
397 Other	Good	x1 15" RCP/ x1 15" corrugated plastic		Dry	Dry	No	No	No	No		RCP	22.61in	2020-06-17 15:09 rockyhill		2020-06-17 15:09 rockyhill	{B528A6C-D555-4286-A710-5371B6D97B23}
398 In Water	Access through residential yard			Standing Water							Corrugated Metal	23.61in	2020-06-17 15:11 rockyhill		2020-06-17 15:11 rockyhill	{F9AEE46D-6112-4D9D-B971-93D6B6B5B071}
399 In Water	Access through residential yard	Far	x2 30" Metal x1 15" RCP	Trickling	Trickling	No	Yes	No	No		Corrugated Metal	24.61in	2020-06-17 15:15 rockyhill		2020-06-17 15:15 rockyhill	{2ED74189-5C1C-45F3-B07F-72F1E146}
400 In Water	In residential yard	18" plastic		Standing Water							Plastic	25.61in	2020-06-17 15:17 rockyhill		2020-06-17 15:17 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
401 In Water	Good	Standing Water	Standing Water	Standing Water	Standing Water	No	Yes	No	No		Concrete	26.61in	2020-06-17 15:30 rockyhill		2020-06-17 15:30 rockyhill	{BBC2D8A8-5BEF-4108-BAF9-6C0D7B1BC1D0}
402 In Water	In abundant foliage	Good	Standing Water	Standing Water	Standing Water	No	Yes	No	No		Concrete	27.61in	2020-06-17 15:36 rockyhill		2020-06-17 15:36 rockyhill	{13000386-5F7C-4033-BF20-45D710D9DE45}
403 Other	Good	15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	28.61in	2020-06-17 15:40 rockyhill		2020-06-17 15:40 rockyhill	{8E1C1408-0A32-423E-B3F3-9A9D0DE7EB3C}
404 Other	Good	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	29.61in	2020-06-17 15:49 rockyhill		2020-06-17 15:49 rockyhill	{A97CB11E-F710-42F2-87b7-8C5D85F9F246}
405 Other	Severely blocked	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	30.61in	2020-06-17 15:51 rockyhill		2020-06-17 15:51 rockyhill	{C72B9D3b-3B6C-4995-8110-6B0B2BF108BF}
406 Other	In residential yard	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	31.61in	2020-06-17 15:58 rockyhill		2020-06-17 15:58 rockyhill	{1E05667B-E049-494F-BC97-AF04B8F2575}
407 Other			Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	32.61in	2020-06-17 16:00 rockyhill		2020-06-17 16:00 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
408 In Water	Good	15" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	33.61in	2020-06-17 16:05 rockyhill		2020-06-17 16:05 rockyhill	{D01171c-1914-4650-914A-7C1D57914183}
409 Other	In abundant foliage	Far		Dry	Dry						RCP	34.61in	2020-06-17 16:23 rockyhill		2020-06-17 16:23 rockyhill	{2C891FCD-13A9-4CRE-9EC4-01CB5661AD0}
410 Near Bank	In abundant foliage	Far	15" RCP	Dry	Dry	No	No	Yes	No		RCP	35.61in	2020-06-17 16:33 rockyhill		2020-06-17 16:33 rockyhill	{C2EC05bC-C447-4 1CE-B184-BB3B6B6B812}
411 Other	In residential yard			Dry	Dry						RCP	36.61in	2020-06-17 16:35 rockyhill		2020-06-17 16:35 rockyhill	{1AA833AE-E1D3-4513-BC4F-C482bF0D33F4}
412 In Water	Good	20" RCP	Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	37.61in	2020-06-17 16:00 rockyhill		2020-06-17 16:00 rockyhill	{29AF7F1C-8E5D-4C7F-AAD4-588A28EF9E5B}
413 Other	Good	20" RCP	Dry	Dry	Dry	No	No	No	No		RCP	38.61in	2020-06-17 17:02 rockyhill		2020-06-17 17:02 rockyhill	{A2B49A2-D89A-49DD-9E90-3317EBB2B839}
414 Other	Good	15" RCP	Trickling	Trickling	Trickling	No	No	Yes	No		RCP	39.61in	2020-06-17 17:05 rockyhill		2020-06-17 17:05 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
415 Other	Could not locate			Dry	Dry						Plastic	40.61in	2020-06-17 17:29 rockyhill		2020-06-17 17:29 rockyhill	{7D2A537b-2C11-47DF-A0C1-9E0B3AAE3C2C}
416 Other	Could not locate			Dry	Dry						Plastic	41.61in	2020-06-17 17:34 rockyhill		2020-06-17 17:34 rockyhill	{CA3C4F60-5301-1463-A03C-8CB72031387b}
417 In Water	Good	Trickling	Trickling	Trickling	Trickling	No	No	No	No		Concrete	01.61in	2020-06-17 12:45 rockyhill		2020-06-17 12:45 rockyhill	{AFA72B-3C2A-4111-8F6b-FFD9F9F9CF7B9}
418 In Water	Good	Trickling	Trickling	Trickling	Trickling	No	No	No	No		Concrete	02.61in	2020-06-17 12:46 rockyhill		2020-06-17 12:46 rockyhill	{557B860-2A4F-468A-803D-5D4B6F58A09F}
419 In Water	Along residential property	24" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	03.61in	2020-06-17 12:52 rockyhill		2020-06-17 12:52 rockyhill	{2224289B-9924-4F99-987A-FD6B5179C703}
420 Other	Along residential property	20" RCP	Dry	Dry	Dry	No	No	No	No		RCP	04.61in	2020-06-17 12:58 rockyhill		2020-06-17 12:58 rockyhill	{B6DD0688-3628-434C-B4A6-AEBE2B89501C}
421 In Water		15" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	05.61in	2020-06-17 13:01 rockyhill		2020-06-17 13:01 rockyhill	{59F4EB1b-2DC4-1Ab9-BCC4-B8B7B6D35A7}
422 On Bank	Good	20" clay	Moderate	Moderate	Moderate	No	No	No	No		Clay Tile	06.61in	2020-06-17 13:52 rockyhill		2020-06-17 13:52 rockyhill	{B980A3A6-A4E4-4657-9C0F-00FD0156B5E3}
423 Other	Good	15" RCP	Dry	Dry	Dry	No	No	No	No		Corrugated Metal	07.61in	2020-06-17 13:54 rockyhill		2020-06-17 13:54 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
424 Other	In residential yard	x1 30" Metal x1 25" RCP		Trickling	Trickling						Corrugated Metal	08.61in	2020-06-17 13:57 rockyhill		2020-06-17 13:57 rockyhill	{B6F6F5b8-B6B8-4C87-B6D8-E1D81C19B6D}
425 Other	In residential yard			Standing Water							Corrugated Metal	09.61in	2020-06-17 13:10 rockyhill		2020-06-17 13:10 rockyhill	{A7BE1599-3C43-410D-B04D-F5464061072D}
426 Near Bank	Downhill	24" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	10.61in	2020-06-17 13:15 rockyhill		2020-06-17 13:15 rockyhill	{10ED2F7b-313b-4D3E-89FF-FD05B39A0AA}
427 Other	Severely blocked	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	11.61in	2020-06-17 13:21 rockyhill		2020-06-17 13:21 rockyhill	{10A3DDF4-6A00-4641-856E-AEBE2F1AD130}
428 Other	Good	15" RCP	Dry	Dry	Dry	No	No	Yes	No		RCP	12.61in	2020-06-17 13:22 rockyhill		2020-06-17 13:22 rockyhill	{7267162D-17B0-4BE9-BE7C-0431-1EA91F8}
429 In Water	Slightly downhill	15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	13.61in	2020-06-17 13:26 rockyhill		2020-06-17 13:26 rockyhill	{C4116222-F785-448B-A860-696415f9F4BE}
430 Other	Severely blocked	15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	14.61in	2020-06-17 13:40 rockyhill		2020-06-17 13:40 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
431 Other	In residential yard			Dry	Dry						RCP	15.61in	2020-06-17 13:42 rockyhill		2020-06-17 13:42 rockyhill	{B3F1CF2-1525-4956-B7F9-B6B1B2B6115}
432 Other	Severely blocked	Far	15" RCP	Dry	Dry	No	No	Yes	No		RCP	16.61in	2020-06-17 13:47 rockyhill		2020-06-17 13:47 rockyhill	{1B28F2D2-12E8-83D3-A93D-4911ABE16138}
433 Other	In residential yard			Dry	Dry						RCP	17.61in	2020-06-17 13:58 rockyhill		2020-06-17 13:58 rockyhill	{27B3BAA4-E87f-4A0A-9005-99F7522780C}
434 Other	In abundant foliage			Dry	Dry						RCP	18.61in	2020-06-17 14:06 rockyhill		2020-06-17 14:06 rockyhill	{4D43EF6D-F264-4255-8F10-4BDB8AAAF505}
435 In Water	Good	20" RCP	Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	19.61in	2020-06-17 14:07 rockyhill		2020-06-17 14:07 rockyhill	{41D0260-1B89-43E2-BE2C-41E4E8B07F1}
436 In Water	Good	x2 30" & x1 15" corrugated metal/ x1 15" RCP	Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	20.61in	2020-06-17 14:09 rockyhill		2020-06-17 14:09 rockyhill	{F03F3F8A-A089-4CA7-8A24-434207C7DC36}
437 In Water	Good	20" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	21.61in	2020-06-17 14:12 rockyhill		2020-06-17 14:12 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
438 In Water	Good	20" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	22.61in	2020-06-17 14:40 rockyhill		2020-06-17 14:40 rockyhill	{B4A6CF8-A8TD-4C3-A5B1-1F4812746F9A}
439 Other	Good	30" RCP	Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	23.61in	2020-06-17 14:55 rockyhill		2020-06-17 14:55 rockyhill	{2C1BF5D5-BC4A-4F37-B94B-AC4DE12B73C6}
440 In Residential yard				Trickling	Trickling						Plastic	24.61in	2020-06-17 14:57 rockyhill		2020-06-17 14:57 rockyhill	{5B86BFF3-FF04-4F6E-8862-C5F6A3444AC3}
441 In Water	Good	20" RCP	Standing Water	Standing Water	Standing Water	No	No	No	No		RCP	25.61in	2020-06-17 15:06 rockyhill		2020-06-17 15:06 rockyhill	{B4591ECf-27A7-412E-A482-8A1B5B95C0A9}
442 In Water	Good	20" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	26.61in	2020-06-17 15:07 rockyhill		2020-06-17 15:07 rockyhill	{F1A0A71-C383-4AC5-B017-4903E7181C02}
443 Other	Severely blocked	Far	15" RCP	Dry	Dry	No	No	No	No		RCP	27.61in	2020-06-17 15:10 rockyhill		2020-06-17 15:10 rockyhill	{B2DE54F-3149-6526-83b3-158E9513C5F2}
444 Other		15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	28.61in	2020-06-17 15:21 rockyhill		2020-06-17 15:21 rockyhill	{99F64b5b-1866-AAF8-B0B1-AF9B3DB61B0D}
445 Other	Good	15" RCP	Dry	Dry	Dry	No	No	No	No		RCP	29.61in	2020-06-17 15:24 rockyhill		2020-06-17 15:24 rockyhill	{A49601C-92CF-4F98-AF9C-302E8D5AF0AE}
446 Other	In residential yard	15" corrugated plastic		Dry	Dry						RCP	30.61in	2020-06-17 15:26 rockyhill		2020-06-17 15:26 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
447 Other	Far	12" RCP	Dry	Dry	Dry	No	No	No	No		RCP	31.61in	2020-06-17 15:29 rockyhill		2020-06-17 15:29 rockyhill	{7F0264B6-2E4A-4716-B02B-2C02378F85A5}
448 Other	In residential yard			Dry	Dry						RCP	32.61in	2020-06-17 15:33 rockyhill		2020-06-17 15:33 rockyhill	{A7D1424B-BC5B-4BC1-A287-3F14E7BED05}
449 Other	In residential yard/abundant foliage			Dry	Dry						RCP	33.61in	2020-06-17 15:41 rockyhill		2020-06-17 15:41 rockyhill	{9ABF41D0-53A5-4C2d-91-C-5933B8BF966}
450 Other	In residential yard			Dry	Dry						RCP	34.61in	2020-06-17 15:44 rockyhill		2020-06-17 15:44 rockyhill	{81270D03-A4AA-4A4F-8129-5039D07d5A30}
451 Near Bank	Good	25" RCP	Dry	Standing Water	Standing Water	No					RCP	35.61in	2020-06-17 15:46 rockyhill		2020-06-17 15:46 rockyhill	{5330F59-8799-45C3-9A28-E59A26EAAA9F}
452 In Water	Far	20" RCP	Trickling	Trickling	Trickling	No	No	No	No		RCP	36.61in	2020-06-17 15:56 rockyhill		2020-06-17 15:56 rockyhill	{8EB4A4D5-229F-4ACF-9CA7-CF2780751195}
453 In Water	Good	20" RCP	Trickling	Trickling	Standing Water	No	No	No	No		RCP	37.61in	2020-06-17 15:58 rockyhill		2020-06-17 15:58 rockyhill	{A7A7A7A7-A7A7-4F0B-A7A7-A7A7A7A7A7A7}
454 Other	Good	x2 20" RCP	Dry	Dry	Dry	No	No	No	No		RCP	38.61in	2020-06-17 16:02 rockyhill		2020-06-17 16:02 rockyhill	{2